



24th April 2019

Dear Matt,

Thank you for the purchase of our 911 Carrera 3.0 (ROP 290R) Listed below is all of the rectification work we carried out to the car as part of our sales process.

I hope you enjoy the car and if you have any problems, please do give me a call.

Lubricate passenger window as it is sticking
Investigate and rectify headlight washers
not working.

Investigate heater control unit not
working correctly.

Fit missing screws on rear parcel shelf

Fit missing drivers door screw cap cover

Investigate inertia seat belt not working

Re-glue trim inside passenger door pocket

Investigate and rectify wipers do not
self park

Investigate and rectify wipers are
intermittent on faster setting

Investigate engine bay seal not
fitting correctly

Re-glue engine bay sound deadening pad
on nearside

Re-glue offside sound deadening

Rectify bonnet light not working

Adjust clock

Secure Nearside front indicator light
unit loose

Adjust Nearside front wheel bearing

Replace offside number plate light unit as
this is cracked

Re-apply underseal to various parts
of underside

Carry out minor service

Investigate and rectify sunroof not working

Offside washer jet not working

Adjust gear linkages

Rectify oil level gauge reading

Rectify drivers seat not locking on its own

Remove air-con controls as air-con unit has
been removed

Carry out geo (car pulls to the left)

Repair and repaint corrosion on front wing

Remove front fog lights and fill in gaps in
front valance

Carry out MOT

Yours Sincerely,

Tom Wood