

# **Vehicle History Report**

### **VEHICLE DETAILS**

Chassis number <sup>1</sup> :	MR41S-636882	Title information <sup>2</sup> :	<b>1</b>	Deregistered to Export	0
Manufacture date:	2018-07-20		<b>u</b> _	-	
Make:	SUZUKI	Accident / Repair:	<b>I</b> ⇒	No problem	$\sim$
Model:	HUSTLER	Odometer rollback:		No problem	
Body:	DAA-MR41S	Manufacturer	~		
Grade:	X TURBO	recall:	۲	Problem found	×
Engine:	R06A-WA04A	Safety grade <sup>3</sup> :	8	****	0
Drive:	2WD	Contamination			
Transmission:	AT	risk:	Å	No problem	$\checkmark$

### This vehicle does not qualify for Buyback Guarantee

#### **Average Market Price**



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.



About Buyback Guarantee

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-02-25 17:32:00. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


## ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

### **ODOMETER READINGS HISTORY**

Date reported	Data source	Odometer reading (Km)
2021-07-09	MLIT	28000
2023-07-21	MLIT	59300
2024-09-04	USS Fukuoka	64810
2024-11-12	TAA Kyushu	64821
2024-11-18	lppatsu Stock	64821
2025-02-08	USS Kyushu	64821

# **USE HISTORY**



2021-07-09		28000	MLIT	Inspection
2023-07-21	Hyogo	59300	MLIT	Inspection
2024-09-04	Fukuoka	64810	USS Fukuoka	Auctioned
2024-11-12	Fukuoka	64821	TAA Kyushu	Auctioned
2024-11-18		64821	Ippatsu Stock	Auctioned
2025-02-08	Saga	64821	USS Kyushu	Auctioned
2025-02-21	Hyogo		MLIT	Last registration

### MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
2019-04-18	MLIT	Other (Other)	There is a possibility that the inspection on the security standards of the road transport vehicle has not been conducted properly because the unqualified inspector (inspection assistant) made a pass / fail judgment, etc. and the acceptance / rejection judgment in the completion inspection process was unclear. is there.


### VEHICLE ASSESSMENT •

### **Overall Collision Safety Ratings**

Driver's seat				Front passeng	er's seat
Points	Evaluation	Goal average	Points	Evaluation	Goal average
8.49	***	71%	10.52	****	88%

\* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

### Braking performance tests <sup>7</sup>



# VEHICLE SPECIFICATION

1st gear ratio		2nd gear ratio	
3rd gear ratio		4th gear ratio	
5th gear ratio		6th gear ratio	
Additional notes		Airbag position, capacity	
Body rear overhang		Body type	LIGHT - RV
Chassis number embossing position		Classification code	6
Cylinders		Displacement	650
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	52PS(38KW)/6500RPM	Engine maximum torque	64KG*M(630NM)/4000RPM
Engine model	R06A-WA04A	Frame type	
Front shaft weight	520	Front shock absorber type	MCPHERSON STRUT COIL SPRING
Front stabilizer type		Front tires size	165/60R15 77H
Front tread	1290	Fuel consumption	
Fuel tank equipment	27	Grade	X TURBO
Height	166	Length	339
Main brakes type		Make	SUZUKI
Maximum speed		Minimum ground clearance	
Minimum turning radius	4600	Model	HUSTLER
Model code	DAA-MR41S	Mufflers number	
Rear shaft weight	300	Rear shock absorber type	I.T.L.( ISOLATED TRAILING LINK ) TYPE COIL SPRING
Rear stabilizer type		Rear tires size	165/60R15 77H
Rear tread	1290	Reverse ratio	3.771

Riding capacity	4	Side brakes type	
Specification code	18096	Stopping distance	
Transmission type	AT	Weight	790
Wheel alignment	2WD	Wheelbase	2425
Width	147		

# AUCTION DATA

### Date: 2024-09-04, Auction: USS Fukuoka, Lot #: 2562

Date:	2024-09-04	Lot #:	2562
Auction name:	USS Fukuoka	Region:	Fukuoka
Make:	SUZUKI	Model:	HUSTLER
Reg. year:	2018	Mileage (km):	64810
Displacement (cc):	660	Transmission:	IA
Color:	PINK 2	Model code:	MR41S
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

### Date: 2024-11-12, Auction: TAA Kyushu, Lot #: 3062

Date:	2024-11-12	Lot #:	3062
Auction name:	TAA Kyushu	Region:	Fukuoka
Make:	SUZUKI	Model:	HUSTLER
Reg. year:	2018	Mileage (km):	64821
Displacement (cc):	660	Transmission:	IAT
Color:	PINK 2	Model code:	MR41S
Result:	unsold	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

### Date: 2024-11-18, Auction: lppatsu Stock, Lot #: 3040

Date:	2024-11-18	Lot #:	3040
Auction name:	lppatsu Stock	Region:	
Make:	SUZUKI	Model:	HUSTLER
Reg. year:	2018	Mileage (km):	64821
Displacement (cc):	660	Transmission:	IAT
Color:	PINK 2	Model code:	MR41S
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

# Date: 2025-02-08, Auction: USS Kyushu, Lot #: 55036

Date:	2025-02-08	Lot #:	55036
Auction name:	USS Kyushu	Region:	Saga
Make:	SUZUKI	Model:	HUSTLER
Reg. year:	2018	Mileage (km):	64821
Displacement (cc):	660	Transmission:	IA
Color:	PINK 2	Model code:	MR41S
Result:	available	Auction grade:	4.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

# PHOTOS AND AUCTION SHEETS

ファーストコーナー

	車整(無非用出外は定入) 排充			660		t Daa-NR	AE		
2562	初日10月 年 名 H30 7月 ハス*		5-	646-1778 5D	クレード Xターボ		2HD	4. )	
∎¥e R	7 # 7	<b>A</b> 24	日 971	LA	T	第 5 第 カワ			
差行 64,810 km			<b>*</b> 1	5 AAC					
1 元8 8日 2 ビンク2 _ 2 ガソリン 「		DAE	-	EVEDIA (MEDIA) + EVENCBET		-7174	ーキサポート フルセグTV		
		4.8				<ul> <li>・全方位モニター用カメラパッケージ</li> <li>・社外エアロ、マフラー、足回り</li> </ul>			
a and	A 2 3	AZE	-	BESSAN M		· 229-16-1	ンチル、ティリ酸化ライブ	ールレンズ	
サイクル	8, 400 19	B	<b>WAR</b>		# h	ナン後			
			4		# W	<b>MR41S</b> -	636882		
. HIDA W K	511 .74	KILL		597	別曲				

- ・HIDヘッドライト ・アイドリングストップ ・単検 約年7月24日送 ・シートビーター ・シートカパー ・ブッシュスタート ・スマートキー ・検正ML、起動り、マフラー、テールレンズ車載

#### O被意具新的

ルーム内うす汚れ


追加メーター取付(エアコン吹出口加工)

×


(08)

.

× の高さ




[周台内寸]的



A:キズ U:ヘコミ B:キズを伴うヘコミ P:要塗装 W:補修跡 S:錆 C:腐食 G:フロントガラス点キズ XX:交換済み X:要交換 内・外装評価 5段階ランク順(A・B・C・D・E) 1





A:キス、U:ヘコミ B:キス、を伴うヘコミ P:要塗装 W:補修跡 S:錆 C:腐食 G:フロントガラス点キス、XX:交換済み X:要交換 内・外装評価 5段階ランク1頃(A+B+C+D+E) 1




	単語( <u>単単物の外組入)</u> 第2       		660		DAA-NR41S		AE	
55036				1F78 クレー 50	・ド Xターポ	licin 2110	4. )	
EN R	7 年 71	98	シフト	IAT	割 第 第 カワ		K) (M FE) (17	
走行 64,815 km					セールスポイント ブッシュスタート・スマートキー Bインチナビ・フルセグTY 全方位モニター			
(元8 1911) カラー& B ピンク2 → DAE ガソリン <sup>9 ■ 8</sup>								
* -	) ) ) ) ) ) )	ハンドル	111918A		前後ドライ	プレコー	ダー ーキサポート	
19121	, 400 P				佐賀	581 な	4251	
				草台胞	636882			

純正パーツ車内積込分

### 0秋田長和台

シートカバー取付 ルーム内うす汚れ ボディー部うすキズ有り



[周台内寸]約 ×

×

ce 高さ

(08)

.

<sup>1</sup> Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

### <sup>2</sup> Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan , the vehicle is determined to be exported

<sup>3</sup> Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

<sup>4</sup> **Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

<sup>5</sup> Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

<sup>6</sup> Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test , rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

<sup>7</sup> **Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.