

Vehicle History Report

VEHICLE DETAILS

Chassis number 1: RP3-1012416 Manufacture date: 2015-06-23

Make: **HONDA**

Model: STEPWGN SPADA

DBA-RP3 Body:

Grade: **SPADA**

Engine: L₁₅B

Drive: 2WD

Transmission: AΤ Title information ²:

Deregistered to **Export**

Accident / Repair:



No problem

Odometer rollback:



No problem

Manufacturer recall:



Problem found

Safety grade ³:



Contamination risk:



No problem

This vehicle does not qualify for Buyback Guarantee

Average Market Price



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.



¥1,700,000

About Buyback Guarantee

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2025-01-18 19:53:05. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2018-01-08	Honda Kansai	25960
2018-02-08	KMAA	25960
2019-04-29	JU Kyouyuu	26000
2021-09-27	MLIT	36900
2023-09-26	MLIT	48400
2024-12-02	JU Kyouyuu	53832
2024-12-13	JU Fukuoka	53957
2024-12-19	KCAA Fukuoka	53957

USE HISTORY

DETAILED HISTORY

Event date Location Odometer reading (Km) Data source Details

2015-06-23			HONDA	Manufactured
2015-06			MLIT	First registration
2018-01-08	Hyogo	25960	Honda Kansai	Auctioned
2018-02-08		25960	KMAA	Auctioned
2019-04-29		26000	JU Kyouyuu	Auctioned
2021-09-27		36900	MLIT	Inspection
2023-09-26	Fukuoka	48400	MLIT	Inspection
2024-12-02		53832	JU Kyouyuu	Auctioned
2024-12-13	Fukuoka	53957	JU Fukuoka	Auctioned
2024-12-19	Fukuoka	53957	KCAA Fukuoka	Auctioned
2025-01-10	Fukuoka		MLIT	Last registration

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
2018-05-31	MLIT	Main brake general	In the brake master cylinder, since the material and shape of the secondary cup are inappropriate, the cup swells due to the plasticizer dissolved in the brake fluid from the reservoir tank hose, and when the cup expands due to the heat influence from the running engine, It may be deformed. For this reason, the sealing performance is deteriorated, and when the brake pedal is slowly depressed, the brake fluid leaks from the seal portion, and in the worst case, there is a fear that the braking distance becomes long.

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
11.17	****	93%	11.4	****	95%

^{*} In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points

but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road 41.8 m

Wet road 41.4 m

VEHICLE SPECIFICATION

1st gear ratio		2nd gear ratio	
3rd gear ratio		4th gear ratio	
5th gear ratio		6th gear ratio	
Additional notes		Airbag position, capacity	
Body rear overhang		Body type	MV&1BOX
Chassis number embossing position		Classification code	13
Cylinders	4	Displacement	1490
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	150PS(110KW)/5500RPM	Engine maximum torque	207KG*M(2030NM)/1600RPM ~5000
POWEI		•	
Engine model	L15B	Frame type	
•	L15B 930	·	MCPHERSON
Engine model		Frame type Front shock	MCPHERSON 205/60R16 92H
Engine model Front shaft weight		Frame type Front shock absorber type	
Engine model Front shaft weight Front stabilizer type	930	Frame type Front shock absorber type Front tires size	
Engine model Front shaft weight Front stabilizer type Front tread	930	Frame type Front shock absorber type Front tires size Fuel consumption	205/60R16 92H
Engine model Front shaft weight Front stabilizer type Front tread Fuel tank equipment	930 1470 52	Frame type Front shock absorber type Front tires size Fuel consumption Grade	205/60R16 92H SPADA

Minimum turning radius	5400	Model	STEPWGN SPADA
Model code	DBA-RP3	Mufflers number	
Rear shaft weight	770	Rear shock absorber type	AXLE TYPE
Rear stabilizer type		Rear tires size	205/60R16 92H
Rear tread	1485	Reverse ratio	1.858 ~1.264
Riding capacity	8	Side brakes type	
Specification code	18043	Stopping distance	
Transmission type	AT	Weight	1690
Wheel alignment	2WD	Wheelbase	2890
Width	169		

AUCTION DATA

Date:

Make:

Reg. year:

Auction name:

Date: 2018-01-08, Auction: Honda Kansai, Lot #: 70294

Date: 2018-02-08, Auction: KMAA, Lot #: 60003

2018-02-08

KMAA

HONDA

2015

Date:	2018-01-08	Lot #:	70294
Auction name:	Honda Kansai	Region:	Hyogo
Make:	HONDA	Model:	STEPWGN SPADA
Reg. year:	2015	Mileage (km):	25960
Displacement (cc):	1500	Transmission:	DAT
Color:	BLACK	Model code:	RP3
Result:	unsold	Auction grade:	3.5
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

Lot #:

Region:

Model:

Mileage (km):

60003

25960

STEPWGN SPADA


Displacement (cc):	1500	Transmission:	IA		
Color:	BLACK	Model code:	RP3		
Result:	sold	Auction grade:	4		
Problem type:	No problem	Problem scale:	None		
Contaminated:	No	Airbag:	ОК		
Date: 2019-04-29, Auction: JU Kyouyuu, Lot #: 468					
Date:	2019-04-29	Lot #:	468		
Auction name:	JU Kyouyuu	Region:			
Make:	HONDA	Model:	STEPWGN SPADA		
Reg. year:	2015	Mileage (km):	26000		
Displacement (cc):	1500	Transmission:	CVT		
Color:	BLACK	Model code:	RP3		
Result:	available	Auction grade:	4		
Problem type:	No problem	Problem scale:	None		
Contaminated:	No	Airbag:	ОК		
Date: 2024-12-02, Auction	: JU Kyouyuu, Lot #:	40567			
Date:	2024-12-02	Lot #:	40567		
Auction name:	JU Kyouyuu	Region:			
Make:	HONDA	Model:	STEPWGN SPADA		
Reg. year:	2015	Mileage (km):	53832		
Displacement (cc):	1500	Transmission:	CVT		
Color:	BLACK	Model code:	RP3		
Result:	available	Auction grade:	4		
Problem type:	No problem	Problem scale:	None		
Contaminated:	No	Airbag:	OK		
Date: 2024-12-13, Auction	: JU Fukuoka, Lot #:	58			
Date:	2024-12-13	Lot #:	58		
Auction name:	JU Fukuoka	Region:	Fukuoka		

Make:	HONDA	Model:	STEPWGN SPADA
Reg. year:	2015	Mileage (km):	53957
Displacement (cc):	1500	Transmission:	DAT
Color:	BLACK	Model code:	RP3
Result:	unsold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

Date: 2024-12-19, Auction: KCAA Fukuoka, Lot #: 77

Date:	2024-12-19	Lot #:	77
Auction name:	KCAA Fukuoka	Region:	Fukuoka
Make:	HONDA	Model:	STEPWGN SPADA
Reg. year:	2015	Mileage (km):	53957
Displacement (cc):	1500	Transmission:	DAT
Color:	BLACK	Model code:	RP3
Result:	negotiate sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK

PHOTOS AND AUCTION SHEETS



















VXM-135VFNI


























TORUNAGA






























































GLOSSARY

1 Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

- ⁴ Use in the contaminated regions The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.
- ⁵ Radioactive contamination test radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT - Ministry of Land, Infrastructure, Transport and Tourism.

- ⁶ Japan New Car Assessment Program the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.
- ⁷ Braking Performance Tests Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2025 Car VX Limited. All rights reserved.