

Work  
Carried out  
in August 2017.

INVOICE WITH CUSTOMER.

**SLSHOP**

OWNER SERVICES | PARTS STORE | EXPERIENCE

Units 1A, 2, 3 & 4B Drayton Manor Farm Buildings  
Drayton Manor Drive, Stratford Upon Avon  
Warwickshire CV37 9RQ  
t: 01789 337 070  
e: sales@theslshop.com  
www.theSLshop.com

## ESTIMATE PROFORMA

*Paul*

Mr Julian Muggridge  
Orchard House  
21 West End  
Tetbury  
Gloucestershire  
GL8 8NE

**Estimate Date:** 06/07/2017  
**Valid To:** 05/08/2017

Work proposed for Mercedes 300 SI SI 3.0 Convertible Automatic Petrol

Registration Number: 60MSX

Chassis Number: WDB1070412A081441

Estimate Details: Stage 1Mechanical

|                                     |                  |
|-------------------------------------|------------------|
| Labour                              | 4,131.70         |
| Parts, Materials & Additional Items | 5,610.24         |
| Additional Discount                 | (0.00)           |
|                                     | <hr/>            |
|                                     | 9,741.94         |
| VAT @ 20%                           | 1,937.39         |
|                                     | <hr/>            |
| <b>TOTAL</b>                        | <b>11,679.33</b> |
|                                     | <hr/>            |

Work proposed for Mercedes 300 SI SI 3.0 Convertible Automatic Petrol

Registration Number: 60MSX

Chassis Number: WDB1070412A081441

### **LABOUR**

|                                                                                          |          |
|------------------------------------------------------------------------------------------|----------|
| Diagnose and report on slightly lumpy on start up                                        | 79.00    |
| Diagnose and report on Tappety engine ,frt timing seal leak and r/c gaskets leaking      | 237.00   |
| Diagnose and report on Passenger window clunks                                           | 158.00   |
| Remove gearbox and replace rear main seal , and carry out gear box service while removed | 948.00   |
| Replace Radiator and waterpump due to leaks replace antifreeze                           | 513.50   |
| Replace Power steering pump and belt and new fluid                                       | 276.50   |
| Replace rear shocks and mounts                                                           | 197.50   |
| Replace rear discs and pads                                                              | 158.00   |
| Replace exhaust back box clamps and mounts (badley welded )                              | 158.00   |
| Clean fuel pump metal link pipe very rusty                                               | 39.50    |
| Replace engine mountings                                                                 | 181.70   |
| Replace front antiroll bar bushes                                                        | 79.00    |
| Repalce front subframe bushes                                                            | 197.50   |
| Replace wiper blades                                                                     | 15.80    |
| Replace body side mouldings both sides and new fixings                                   | 197.50   |
| Replace Hazard switch                                                                    | 23.70    |
| Remove and refit handbrake cover (See Extras)                                            | 79.00    |
| Remove and refit battery clamp                                                           | 7.90     |
| Replace heater valve and check for leaks.                                                | 79.00    |
| Tidy up HT Leads                                                                         | 31.60    |
| Replace N/S Hardtop seal                                                                 | 39.50    |
| RE Glue boot seal                                                                        | 158.00   |
| Replace deck seal ripped                                                                 | 237.00   |
| Replace Header rail O-rings                                                              | 39.50    |
| Total:                                                                                   | 4,131.70 |

### **Advisory**

### **LABOUR**

**Grand total: 4,131.70**

### **PARTS & MATERIALS**

|   |             |       |          |
|---|-------------|-------|----------|
| 1 | 000310      | PARTS | 2,756.04 |
|   | Parts Total |       | 2,756.04 |

### **Additional Items**

|                       |        |
|-----------------------|--------|
| Paint hard top/repair | 950.00 |
|-----------------------|--------|

|                                                       |          |
|-------------------------------------------------------|----------|
| Refurb handbrake cover                                | 180.00   |
| Fit new soft top roof (Black)                         | 659.20   |
| Consumables                                           | 150.00   |
| Full detail Engine, interior, paint and showroom prep | 350.00   |
| MOT                                                   | 55.00    |
| Fuel                                                  | 30.00    |
| Number plate supply and fit                           | 15.00    |
| Waste Oil Disposal                                    | 15.00    |
| Underbody wax/oil from Welding                        | 450.00   |
| Extras Total                                          | 2,854.20 |

---

**11,679.33**

---

### **Parts Disclaimer**

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customers statutory rights.

All goods shall remain the property of the seller until paid for in full.