

Check MOT history

This is a new service - Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX? vrm=A724AMK&make result=PORSCHE&model result=911&mot first used date=1984-04-17&vehicle age=14241&mot expiry date=2023-07-

28&mot expiry date days left=105&user satisfaction banner=0&vehicle data origin=MTS&vehicle type=LGV) to help us improve.

< Back



PORSCHE 911

Check another vehicle (/)

Colour

White

Fuel type

Petrol

Date registered

17 April 1984

MOT valid until

28 July 2023

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-v5c?registration=A724AMK)

If you think the MOT expiry date or any of the vehicle details are wrong: contact DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes).

A Hide all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

Hide

Date tested 22 July 2022

PASS

Mileage

70,477 miles

Test location

View test location

MOT test number

6559 3626 3151

Expiry date

28 July 2023

Date tested

22 July 2022



Mileage

70,477 miles

Test location

View test location

MOT test number

7479 4999 0653

Repair immediately (major defects):

- Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- What are defects?

Date tested

29 July 2021

PASS

Mileage

70,394 miles

Test location

View test location

MOT test number

8115 5556 6710

Expiry date

28 July 2022

Date tested

24 July 2020

PASS

Mileage

68,343 miles

Test location

View test location

MOT test number

8350 5764 0709

Expiry date

23 July 2021

Date tested

16 July 2020

FAIL

Mileage 68,343 miles

Test location

View test location

MOT test number

5312 2208 0445

Do not drive until repaired (dangerous defects):

• Steering wheel likely to become detached (2.2.1 (b) (ii))

Repair immediately (major defects):

- Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Offside Rear fog lamp not working (4.5.1 (a) (ii))
- What are defects?

Date tested

25 July 2019

PASS

Mileage

66,477 miles

Test location

View test location

MOT test number

2996 6994 1025

Expiry date

24 January 2021

Date tested

25 July 2019



Mileage

66,477 miles

Test location

View test location

MOT test number

3402 9162 4603

Repair immediately (major defects):

- Offside Rear fog lamp not working (4.5.1 (a) (ii))
- What are defects?

Date tested

25 May 2018

PASS

Mileage

66,142 miles

Test location

View test location

MOT test number

7895 3957 5181

Expiry date

24 May 2019

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested

24 August 2016

PASS

Mileage

66,038 miles

Test location

View test location

MOT test number

8290 4088 8047

Expiry date

23 August 2017

Date tested

22 June 2016

PASS

Mileage

65,983 miles

Test location

View test location

MOT test number

7439 8569 9998

Expiry date

21 June 2017

Advisory notice item(s)

- Oil leak
- What are advisories?

Date tested

22 June 2016



Mileage

65,978 miles

Test location

View test location

MOT test number

5819 0033 2850

Reason(s) for failure

- Nearside Rear Stop lamp not working puts on n/s/f side light (1.2.1b)
- Rear fog lamp not working (1.3.2b)
- Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advisory notice item(s)

- Oil leak
- What are failures and advisories?

Date tested

5 May 2015

PASS

Mileage

65,123 miles

Test location

View test location

MOT test number

8653 1532 5165

Expiry date

4 May 2016

Advisory notice item(s)

- Nearside Front Lower Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Offside Front Lower Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

- Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- offside front and nearside front wiper blades deteriorating, recommend replacement
- What are advisories?

Date tested

2 May 2014

PASS

Mileage

64,395 miles

Test location

View test location

MOT test number

3368 4252 4111

Expiry date

1 May 2015

Advisory notice item(s)

- Tyre worn close to the legal limit (4.1.E.1)
- What are advisories?

Date tested

24 April 2014

FAIL

Mileage

64,394 miles

Test location

View test location

MOT test number

2663 4401 4112

Reason(s) for failure

- Nearside Rear Seat belt obviously repaired (5.2.2c)
- Driver's door cannot be opened from inside the vehicle (6.2.B.1b)
- Offside Rear fog lamp not working (1.3.2b)
- Nearside Front Brake pipe inadequately supported (3.6.B.1)

Advisory notice item(s)

- Tyre worn close to the legal limit (4.1.E.1)
- What are failures and advisories?

Date tested

2 May 2013



Mileage

63,469 miles

Test location

View test location

MOT test number

4369 9252 3164

Expiry date

1 May 2014

Advisory notice item(s)

- Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Oil leak
- What are advisories?

Date tested

2 May 2013

FAIL

Mileage

63,469 miles

Test location

View test location

MOT test number

5361 8242 3107

Reason(s) for failure

- Hazard warning lamps inoperative (1.4.B.1b)
- Rear fog lamp not working (1.3.2b)

Advisory notice item(s)

- Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Oil leak
- What are failures and advisories?

Date tested

14 April 2010

PASS

Mileage

62,703 miles

Test location

View test location

MOT test number

4441 6450 0147

Expiry date

13 April 2011

Advisory notice item(s)

- Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)
- · slight play in off side inner rack end
- · very slight play in front hubs
- What are advisories?

Date tested

13 April 2010



Mileage

62,703 miles

Test location

View test location

MOT test number

3922 0310 0172

Reason(s) for failure

Nearside Registration plate lamp not working (1.1.5c)

Advisory notice item(s)

- Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)
- slight play in off side inner rack end
- · very slight play in front hubs
- What are failures and advisories?

Check for vehicle recalls

See if PORSCHE 911 A724AMK has outstanding recalls



We do not have recall information for this vehicle.

Contact your local PORSCHE dealership to check if the vehicle has an outstanding recall.

This information is provided by the vehicle manufacturer. If you think the recall information is wrong, contact your local PORSCHE dealership.

<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the **Driver & Vehicle Standards Agency**

OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

