

Check MOT history

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX? vrm=MIB113&make result=MERCEDES-BENZ&model result=280&mot first used date=1969-03-31&vehicle age=19817&mot expiry date=2023-07-</u>

17&mot_expiry_date_days_left=14&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV) to help us improve.

< Back

This vehicle's MOT expires soon

MIB II3

MERCEDES-BENZ 280

Check another vehicle (/)

Colour

Silver

Fuel type

Petrol

Date registered

31 March 1969

MOT valid until

17 July 2023

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

<u>Download test certificates (/enter-v5c?registration=MIB113)</u>

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes)</u>.

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

♠ Hide

Date tested

18 July 2022



Mileage

20,892 miles

Test location

View test location

MOT test number **3692 6617 5773**

Expiry date

17 July 2023

Date tested 11 June 2021

PASS

Mileage 20,715 miles

Test location

View test location

MOT test number 8270 2791 1304

Expiry date 10 June 2022

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested

22 November 2012

PASS

Mileage 17,081 miles

Test location

View test location

MOT test number

2683 6762 2381

Expiry date

21 November 2013

Date tested

22 November 2012



Mileage 17,081 miles

Test location

View test location

MOT test number

3382 5782 2309

Reason(s) for failure

- Rear Stop lamp not working (1.2.1b)
- ▶ What are failures?

Date tested

13 October 2008

PASS

Mileage

79,712 miles

Test location

View test location

MOT test number

2523 7738 8281

Expiry date

12 October 2009

Date tested

13 October 2008



Mileage

79,712 miles

Test location

View test location

MOT test number

8843 3778 8251

Reason(s) for failure

- Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
- Offside Headlamp aim too low (1.8)
- ► What are failures?

Check for vehicle recalls

See if MERCEDES-BENZ 280 MIB113 has outstanding recalls



<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the Driver & Vehicle Standards Agency

OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

