Search for vehicles subject to recalls, improvement measures, and service campaigns [Motorcycles and automobiles]

The purpose of this search system is to provide information on the implementation status of "recalls, improvement measures, and service campaigns" reported to the Ministry of Land, Infrastructure, Transport and Tourism for each vehicle, and to enable the completion of countermeasures as quickly as possible.

You can check whether your vehicle is subject to a recall, improvement measure, or service campaign by using the chassis number.

(Past implementation history is also displayed at the same time)

Enter the information written in the "Chassis Number" field on your "Vehicle Inspection Certificate" in half-width alphanumeric characters and press the "Search" button. <u>How to check the chassis number</u>Please refer to.

| Please enter your chassis number | |
|----------------------------------|--|
| MR31S-804292 | |

SEARCH

Example: HA23S-600001 (half-width alphanumeric characters)

The vehicle with the chassis number you entered is subject to a recall, improvement measures, and service campaign.

[Entered chassis number MR31S-804292]

| | Notification date (notification date) | Contents | Classification | Implementation status |
|----------------------|---------------------------------------|---|----------------|-----------------------|
| No data available | 2018/11/15 | <u>Ene-charge vehicle</u> <u>water pump belt</u> | recall | Completed |
| 2 | 2020/06/18 | <u>Crank pulley bolt for</u> <u>light vehicles</u> | recall | Completed |
| 3 | 2020/11/19 | <u>Hustler Lapin Igniter</u> | recall | Completed |

We sincerely apologize to our valued customers for any inconvenience caused.

If you have any items that have not been inspected, please contact your nearest Suzuki dealer or retailer as soon as possible to have your vehicle inspected and repaired.

Please note that we will need to arrange for parts, so please contact your Suzuki dealer or distributor in advance to inform them of your availability.

♦ After countermeasures are implemented, it may take more than two weeks for the implementation information to be reflected in this search system.

*If you do not know your nearest Suzuki dealer or distributor, please use this site.

- Search for Suzuki dealers
- Motorcycle <u>SUZUKI dealer search</u>