

SC PARTS
SERVICES 0844 1753 882857
933 54570

CONVERSION KIT MGF RUBBER TO CHROME P

Non-standard parts
Modified front bumper
Rear bumper mounting
Modified rear bumper
Standard front valance
Front wing inlets - up
(These need to be v
Front bumper and
Grille - your choice
Slide indicator
Rear bumper
Overriders - v
Number plate
Front valance

Optional
2

Standard parts
Front bumper and
Grille - your choice
Slide indicator
Rear bumper
Overriders - v
Number plate
Front valance

SP
Please do not confuse
Modifications required
Front rubber bumper
Installation, modified
the mounting below
At the rear 2 x 13mm
plates for the rubber

If you do not rec
Destination: *JEK*
From: *JEK*

*To paint
white glass
Fit interior
Under bonnet
Dad
Fills*

29/01 '98 THU 15:21 FAX

SC

13 Cobham W
Austin Healey, 2

Destin
From

Destination:

From:

AMM 6079 -
AMM 5261 C.
Large camera
AMM 6208
209
AMM 69
240
55!

SC

13 Cobham
Austin Healey

Destin
From

PARTS - MGB Roadster

- Cable fixings
- Radio fixing kit not su
- Clutch bearing
- Black aerosol x 4
- Gold paint x 2
- UNF nuts x 2
- HT Bolts x 4
- HT sets x 4
- Studlock
- Headlamp bulbs
- Hose clips
- Sealant
- Interior door ha
- S/hand door k
- Flasher door k
- Brake unit
- Brake fluid
- Dip switch &
- Powersolve
- Sundry ele
- Advanced
- Lubricant
- Milboard
- Aerial ex
- 1.5 mtrs
- Assorte
- MOT
- Lucas
- Electr
- Num
- Div
- Imm
- Br
- Fu
- Tr

Labour 24 @ £35

Parts

- Fan sender
- Anti-freeze
- Thermoste
- Fuel Gau
- Carpet c

CLASSIC and
Pigeon F

Classic Coachbuilders
CLASSIC and SPORTS CAR RESTORERS
(Sole Proprietor: G. Cover)
Pigeon Farm, Bobbing Hill, Bobbing, Nr. Sitt
Telephone & Fax 01795
e-mail classic@coachbuilders

Jeffery.inv1/GC/SS
26th July 2004
Mr J Jeffery

INVOICE - MGB Roadster

- Remove and replace seat belts
- Remove fuel tank sender unit
- Test both units
- Supply later type fuel gauge
- Strip and swap over chrome bezel
- Fit gauge
- Re-fix drivers door lock
- Make up under dash panels an
- Remove and replace interior r
- Strip and fit battery cut off
- Touch in scratch to drivers
- Remove radiator, clean an
- Flush through engine blo
- Re-fit radiator
- Supply and fit fan send
- Supply and fit thermo
- Machine polish and
- Fit quarter light mi

SOLD TO:
MEDITERRANEAN CLAS
2893 ALTAFULLA
TARRAGONA
CATALUNYA
SPAIN

SCP
Specialist Car Products
11 & 12, Fairgate Business Centre
Fairgate, Norwich
West Sussex, RG12 1DN
+44 (0)1263 881777
enquiries@scp-uk.com

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No

HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Wheel shoe set LS1023	1.00	31.71	17.50	17.50	28.84
Brake shoe set LS1023	1.00	27.74	17.50	17.50	27.74
Thermosist (Cooling) Remove & Refit	2.00	3.25	5.85	5.85	6.50
Radiator (Cooling)wire in and fit new Kenlowe fan	1.00	5.85	5.85	5.85	6.50
Fixed Price Sub Total		220.38			220.38
Fixed Price Sub Total		31.69			31.69
Fixed Price Sub Total		252.07			252.07

Order
K/Off
CARR

Part
Part No
GBC1357AF
LRS AF
BLB472

Fixed Price
Description
CLASS 4 MOT TEST

Reg No
Manufacturer
Model
Mileage
Technician
Val Registration No


HE46T
MG
MGB
3293
508 9871 28

Registered Office: 1 Blatchington Road, Hove, BN1 5 1P • Registered No: 04591115 • VAT Registration No: 508 9871 28
EORI No: GB 387 0083 17 000

PAID
17 JUN 2005

Net
VAT
Gross
This cash invoice is due for payment

Description	Qty	Price	Labour Sub Total	VAT %	Net
Wheel cylinder	1.00	31.71	1		



Roger Jackson Ltd

6 Arundel Mews, Brighton, BN2 1GG

Tel: 01273 694294

Car & Light Commercial Servicing, MOT Repairs, Vehicle Collection & Delivery Available

Invoice

Mediterranean Classics

Aitafulla

Tarragona

Spain

Invoice No. 013511

Tax Date 17/06/2005

Account Ref. MED002

Order No.

Job Number

Labour

Description	VAT %	Nett
Brake shoes - rear (axle set) Remove & Refit		
Wheel cylinder assy - rear (osr) Remove & Refit		
Thermostat (Cooling) Remove & Refit		
Radiator (Cooling)wire in and fit new Kenlowe fan.	17.50	112.50
Labour Sub Total		112.50

Parts

Part No.	Description	Qty	Price	VAT %	Nett
GBS1357AF	Brake shoe set LS1023	1.00	31.71	17.50	28.54
GWC1920	Wheel cylinder	1.00	27.74	17.50	27.74
LTRS AF	Antifreeze	2.00	3.25	17.50	6.50
BLB472	Headlight bulb	1.00	5.85	17.50	5.85
Parts Sub Total					68.63

Fixed Price

Description	VAT %	Nett
CLASS 4 MOT TEST	0.00	39.25
Fixed Price Sub Total		39.25

Reg No. HLE546T

Manufacturer MG

Model MGB

Mileage 3293

Technician

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E

Net	220.38
VAT	31.69
Gross	252.07

Vat Registration No. 508 9371 26

This cash invoice is due for payment





Roger Jackson Ltd

6 Arundel Mews, Brighton, BN2 1GG

Tel: 01273 694294

Car & Light Commercial Servicing, MOT Repairs, Vehicle Collection & Delivery Available

Invoice

Mediterranean Classics

Aitafula

Tarragona

Spain

Invoice No. 013511

Tax Date 17/06/2005

Account Ref. MED002

Order No.

Job Number

Labour

Description

VAT %

Nett

Brake shoes - rear (axle set) Remove & Refit

Wheel cylinder assy - rear (osr) Remove & Refit

Thermostat (Cooling) Remove & Refit

Radiator (Cooling) wire in and fit new Kenlowe fan.

17.50 112.50

Labour Sub Total

112.50

Parts

Part No.

Description

Qty

Price

VAT %

Nett

GBS1357AF

Brake shoe set LS1023

1.00

31.71

17.50

28.54

GWC1920

Wheel cylinder

1.00

27.74

17.50

27.74

LTRS AF

Antifreeze

2.00

3.25

17.50

6.50

BLB472

Headlight bulb

1.00

5.85

17.50

5.85

Parts Sub Total

68.63

Fixed Price

Description

VAT %

Nett

CLASS 4 MOT TEST

0.00

39.25

Fixed Price Sub Total

39.25

Reg No. HLE546T

Manufacturer MG

Model MGB

Mileage 3293

Technician

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E

Net

220.38

VAT

31.69

Gross

252.07

Vat Registration No. 508 9371 26

This cash invoice is due for payment



SCP

Specialist Car Products Ltd.

11 & 12, Faygate Business Centre
Faygate, Horsham
West Sussex RH12 4DN
+44 (0)1293 851777
enquiries@scp-uk.com

Manufacturers & Suppliers of
Quality Classic Car Parts
and Alloy Wheels



MINILITE

Beverly Works
Off Holyhead Road
Telford, Shropshire TF1 4DS
+44 (0)1952 620215
sales@minilite.co.uk

Parts Sale Invoice

SOLD TO:
MEDITERRANEAN CLASSICS
ALT CAMP 6A
43893 ALTAFULLA,
TARRAGONA,
CATALUNYA
SPAIN

DELIVER TO:
CLASSIC CHROME LTD
12 SHEEN LANE

MORTLAKE
SW14 8LN

Account No: MECL
Invoice No.: 067550
Sale Date: 09/05/2023
Cust. Ref.: PS115752
Operator: MH
Cust.EORI:

VAT No. ES X4154233L

<u>Part Number</u>	<u>Description</u>	<u>Rec.S.P</u>	<u>Unit Pr</u>	<u>Qty</u>	<u>Back.Ord</u>	<u>Total</u>	<u>V</u>
415	Order Ref. Email Erik						
CARR	K/OFF MINATOR 5.5 x 15 SAO	194.48	125.00	1.00		125.00	1
	CARRIAGE 24/48 HOUR	10.31	10.31	1.00		10.31	1

EORI GB 367 5563 17 000

Payment Type:

ACCOUNT 162.37

Tot. NET 135.31
Tot. VAT 27.06
Total. £ 162.37

Registered in England & Wales No. 1690048 VAT No. GB 367 5563 17

EORI No. GB 367 5563 17 000



Classic Coachbuilders

CLASSIC and SPORTS CAR RESTORERS and COACHBUILDERS
(Sole Proprietor : G. Coveney)

Pigeon Farm, Bobbing Hill, Bobbing, Nr. Sittingbourne, Kent ME9 8PD
Telephone & Fax 01795 844244
e-mail : classic@coachbuilders.fsnet.co.uk

Jeffery.inv1/GC/SS

26th July 2004

Mr J Jeffery

INVOICE - MGB Roadster

Remove and replace seat belts
Remove fuel tank sender unit
Remove fuel gauge
Test both units
Supply later type fuel gauge
Strip and swap over chrome bezel and inner masking
Fit gauge
Re-fix drivers door lock
Fit front footwell carpet clips
Make up under dash panels and trim
Remove and replace interior mirror
Supply and fit battery cut off switch
Strip and fit new hood
Touch in scratch to drivers door
Remove radiator, clean and flush though
Flush through engine block and heater
Re-fit radiator
Supply and fit fan sender unit
Supply and fit thermostat
Fill with new anti-freeze
Machine polish and hand glaze body
Fit quarter light mirror

Labour 24 @ £35.00 £840.00

<u>Parts</u>	£
Fan sender	2.57
Anti-freeze	6.00
Thermostat	1.80
Fuel Gauge	30.00
Carpet clips	6.00

VAT Reg No. 515 9155 43

Black Moquette	5.00	
Battery cut off switch	38.00	
	<hr/>	89.37
		<hr/>
		929.37
V.A.T. @ 17.5%		162.64
		<hr/>
Total		£1092.01
		<hr/>

*Paid with
Thanks.
31/7/04.
[Signature]*

Classic Coachbuilders

CLASSIC and SPORTS CAR RESTORERS and COACHBUILDERS

(Sole Proprietor: G. Coveney)

Pigeon Farm, Bobbing Hill, Bobbing, Nr. Sittingbourne, Kent, ME9 8PD.
Telephone & Fax 01795 844244

PARTS - MGB Roadster

COST

Cable fixings	£7.40
Radio fixing kit not supplied	£22.30
Clutch bearing	£13.37
Black aerosol x 4	£12.00
Gold paint x 2	£6.00
UNF nuts & bolts various	£24.00
HT Bolts x 4	£2.00
HT sets x 4	£2.00
Studlock	£9.00
Headlamp bulbs	£6.00
Hose clips	£15.53
Sealant	£9.75
Interior door handle plastic retainers	£6.00
S/hand door lock rod x 2	£10.00
Flasher unit	£3.50
Brake fluid	£9.00
Dip switch & bracket	£20.00
Powersolve degreaser	£9.90
Sundry electrical items	£31.20
Advance/retard tube & ends	£8.09
Lubricants	£25.00
Millboard	£5.00
Aerial extension lead	£35.00
1.5 mtrs Black carpet	£15.00
Assorted grommets	£10.00
MOT	£28.50
Lucas alternator overhaul	£38.68
Electric aerial	£42.50
Number plates	£32.00
Drive belt	£4.20
Immobiliser	£120.00
Breather T piece	£3.50
Fuel pipe & clips	£12.00
Tenax clips	£5.00
Carriage on parts	£22.00

£625.42

£109.45

VAT @ 17.5%

£734.87

Total

Paint with 1 hour

Mediterranean Classics Erik W. Jeffery

ENGLISH CLASSIC CARS (Austin Healey, Jaguar, M.G., Triumph, Mini)

Apartat de Correus 14, 43893 Altafulla
Tarragona, Catalunya
Espanya

Tel(0034) 977 65 21 47 Fax (0034)977 65 03 16

erikj@mediterraneanclassics.net

www.mediterraneanclassics.net

NIF: X-4154233-L

Fecha: 15 de juliol de 2004

Número: 191

PRESUPUESTO

Cliente:

Josh

JEFFERYJ@parliament.uk

Número

Descripción

Precio(Libras)

Josh's old crock

BHA4737	Oil, water gauge, Fahrenheit, internally lit	39,46
	Note. This is an exchange price and you will be charged a surcharge of 50 pounds until they receive the old unit back. If you don't want to do that, you can buy them outright at 10 pounds more. (I can take it back in August or you can send it).	
WPA4000X	Electric window kit	130,18
R248	Under dash kit, Gerry will make this for you	
TT7962	Battery switch, can be mounted on power side	7,49
BHA4806	rod operated mirror	7,15
GAM115	Door mirror	12,74
GAC0052	Tax holder, fixes with seals to window (not visible)	13,58

suma	210,60
IVA-17.5%	36,86
TOTAL	247,46

Carriage free on orders over 200 pounds.

I can probably recover the VAT in my next quarter; if so, I will reimburse you the difference.

Restauració, vendes i recanvis. Restauración, ventas y recambios

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570

Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: <u>JEACV MG</u>	To: <u>SALLY</u>	
From: <u>ERIC</u>	Date: <u>23 Nov 98</u>	No. Pages:

Sally

Thank you for sending my parts to CLASSIC CARCHUILDERS.
Unfortunately the gear lever 228419 was updated &
BHH 8818 incorrect so I will send them back this week.
I need just a few more items of parts, to be sent to
CLASSIC CARCHUILDERS

AHH 7068 x 1

AHH 7069 x 1

352985A x 13

17H2530 x 2

ARA2634 x 1

13H 391 x 1.

BHH 2273 x 1

FKB 1004 x 1.

BHA 4328 x 1

BHA 4329 x 1.

[normally plastic; if there is a brass option, please supply]

Do not back order, but could
you advise what is not
available.

Many thanks.
E

WE NOW ACCEPT AMERICAN EXPRESS

<http://www.scparts.co.uk> Email: enquiries@scparts.co.uk

Directors: DJ Jeffery EW Jeffery Registered in England No. 1863134 Registered Office: As above

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
 Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
 Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: RON LEACY		To: Ron or SALLY.
From: JRLK.	Date: 17 Nov 98	No. Pages:

Some final parts for the MGB.

Finally b/o.

17 H 7990 X 1. v. urgent now.
 GEX 7493 - cancel b/o.

New items.

- GEX 1002 X 1
- GEX 1004 X 1.
- AHH 6271 X 1.
- AHH 6323 X 1
- AHH 6324 X 1.

17 H 7990.
 AHH 6725

From the large order sent last week. (Can you get an invoice please), to
 AHH 6725, ~~22B419~~, AHH 8818.
 Can you advise availability please?

Finally can you send a S/H speaker made in very good condition please. Send to CLASSIC CARBUILDERS.
 T.U.V.H.
 Regards
 Sntk

WE NOW ACCEPT AMERICAN EXPRESS

<http://www.scparts.co.uk> Email: enquiries@scparts.co.uk

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: <i>RON LEACY</i>		To: <i>RON</i>	
From: <i>SPK</i>	Date: <i>9 NOVEMBER</i>	No. Pages: <i>1</i>	

Ron

A few more numbers, please.

AHH 6216 X 1.

AHH 6217 X 9.

AHH 6218 X 2.

GHF 1222 X 26.

*Can you send to CLASSIC COACH BUILDERS as
before. Many thanks.*

[Signature]

WE NOW ACCEPT AMERICAN EXPRESS

<http://www.scparts.co.uk> Email: enquiries@scparts.co.uk

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570

Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: RON LEACH	To: RON	
From: SPK.	Date: 5 Nov 98	No. Pages: 2

Ron

Further to our telephone conversation
AHC 109 [AHB9982] - EN8 U-bolts £0.35 500
lots.

Can you supply the following please & send to CLASSIC CARCHILDERS

XGA 2917 + chrome strip - possibly s/hand

BD32364 x 2.

22B419 x 1.

22B524 - s/hand if not avail.

AHH 6331 x 1

AHH 6291, 6292 & BDH741 - s/hand if not avail.

4B934 x 4.

GW506 x 1.

AHH 8816 x 1.

AHH 6409 x 2

BHH 2670 x 2

27H 4300 x 2.

WE NOW ACCEPT AMERICAN EXPRESS

<http://www.scparts.co.uk> Email: enquiries@scparts.co.uk

Directors: DJ Jeffery EW Jeffer, Registered in England No. 1863134 Registered Office: As above

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: <u>RON LEACH</u>	To: <u>RON</u>	
From: <u>SRIK</u>	Date: <u>4 NOV 98.</u>	No. Pages:

Ron

More MGB parts please.

5L924 x 1.

5L1137 x 1.

GRH903 x 2.

BHA 4513 x 1

AHH 6277 x 1

BHA 4786 x 1

AHC 97 x 1

BHA 4328 x 1

BHA 4329 x 1.

GSR 135 x 1

[new, please: this is the
second one]

Send to CLASSIC COACHBUILDERS

before.

WE NOW ACCEPT AMERICAN EXPRESS

<http://www.scparts.co.uk> Email: enquiries@scparts.co.uk

regards
Many thanks
SRIK

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: RON LEACH	To: RON	
From: ERIK	Date: 3 NOV. 98	No. Pages:

Ron

Can you send directly to my letter
the following.

- GRK 5007 x 1.
- HZA 5386 x 1
- BTB 183 x 2
- AZA 489/490/491 x 1 each
- TMZ 308 x 6

Address: -

CLASSIC COACHBUILDERS
PIGEON FARM
SHEPPEY WAY
BOBBING, Nr SITTINGBOURNE
KENT ME9 8PD.

T.U.V.M.

Erik

WE NOW ACCEPT AMERICAN EXPRESS

<http://www.scparts.co.uk> Email: enquiries@scparts.co.uk

AMH 6079 - MGB badge ^{Jeany} \$1.95
AMH 5261 C. - MG st. \$3.05 D.B.

Bumper covers kit - \$72.

AMH 6208B front bumper \$38.50 Jeany
209 x 8

AMH 6916 x 2 front o/wheel \$8.75

24G 625K x 4 \$0.35 x 4
554700k

~~AMH 1642 x 2~~ no photo bucket \$0.50 stock.
6217 x 2

Bum 1524 front under plate \$2.45

AMH 5791 rear " " \$3.20

AMH 5804 bumper for above x 4 \$0.45

15" SCP wheel \$46.00

AMH 62612 _____ \$41.75 Jeany

AMH 64892- R.H o/wheel \$8.25

AMH 66902- L.H " " \$8.25

AMH 7278 - bumper filler R.H \$0.90
L.H \$0.90

AMH 7279 - " " " "

AMH 7136 - S.C. stake - \$2.45

DEA 4001 - dorsew x 2

AMH 6270 x 1 (under) \$2.05

AMH 6323 x 4 " \$1.75 GNF 400. x 6. \$0.01

SC913

SC951 ✓

SC171 ✓

SC360 ✓

GROUP LTD
D D
PAR

By:

Terms:

Deliv

Not Denied

Shortage

Admin: %

Sh Amt: 0.00

C=Cancelled:

Notes: CARRIER TO CLASSIC COACHBUILDERS

N=Nil:

Notes: 10.00

Notes:

From: MOSS INTERNATIONAL LTD VICTORIA VILLAS RICHMOND SURREY

DATE 30/09/98

TIME 10:36:58

PICKING LIST CUSTOMER= SOC 709903
PICKING NO = 61483

PAGE NO: 1

No. Pages:

CUSTOMER ORDER NO	PART NUMBER	BIN LOC	QTY TO BX PACK 1	QTY BX 2	QTY BX 3	QTY DESC	Ord+Ln SC
EJ01	PSE10241	BAC2	4	0	0	0 SPLITPIN BRA 88897 18B	
EJ01	BHH9728	DIG6	2	0	0	0 DOOR LOCK GA 88897 13B	
EJ01	ATB4074	DJC1	4	0	0	0 BULT CALIPER 88897 17B	
EJ01	37H3387	DJR3	2	0	0	0 DOORLOCK CLI 88897 14B	
EJ01	AHH6216	DNB1	6	0	0	0 SPACER BUMPE 88897 5B	
EJ01	HZA4304	GHG2	1	0	0	0 SPLASH PANEL 88897 2B	
EJ01	AHH9158	WELN	2	0	0	0 BUFFER-BUMP 88897 10B	
EJ01	GRK5007	UKA5	1	0	0	0 SEALS CALIPE 88897 16B	

END OF CUSTOMER

Queries to UAS

Entered by JAS

Nt Wght

1042gms

exhaust filter 1st

grid mesh under vent

AHH 616 2 x 2

SPEED O CABLES

heater water valve 529d

Wabs, types & nuts

col

fuel cap

let engine bay decab.

battery

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570

Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number 01293 546570

Destination: <i>Moss U.K.</i>	To: <i>JIM</i>	
From: <i>SPK.</i>	Date: <i>9 Oct 98</i>	No. Pages: <i>1.</i>

Ref *ES01*

Thank you for supplying against my order of 28 Sept 98 which you kindly shipped to CLASSIC COACHBUILDERS in Sutton. Can you cancel the outstanding items, not supplied. These are as follows:—

17H 7990B x 2.

BKH 1739 x 1

BMA 4175 x 2

BMA 4966 x 1.

BKH 6426B x 1.

AHH 8462 x 1

BHP 973P x 1

[I think this is a wrong no.]

Many thanks

E

Moss Group Ltd

879950

Worked By: *[Signature]*
 Depot Denied
 Shortage

Terms: Deliv
 Admin: x
 Sh Amt: 0.00

2 boxes

Cancelled: Notes: CARRIER TO CLASSIC COACHBUILDERS
 Notes:
 Nil: Notes:

From: MOSS INTERNATIONAL LTD VICTORIA VILLAS RICHMOND SURREY

DATE 30/09/98 PICKING LIST - CUSTOMER= 800 709903 PAGE NO: 1
 TIME 10:37:58 PICKING NO = 61404

CUSTOMER PART ORDER NO NUMBER	BIN LOC	QTY TOBX PACK 1	QTY BX 2	QTY BX 3	QTY DESC	Grd+Ln 90
EJ01 AHH5018K	1AV02	2	0	0	0 REAR SHACKLE 88897 7B	/
EJ01 AHH7854	1BQ02	1	0	0	0 G/BOX MNTG 8 88897 21B	/
EJ01 8G8642	1D001	4	0	0	0 CALIPER PIST 88897 15B	/
EJ01 BHH1619	2EB02	1	0	0	0 ENG MNTG BRK 88897 19K	/
EJ01 AHH7334	3BP03	4	0	0	0 SPRING PLATE 88897 6B	/
EJ01 NRP1154	3PALL	1	0	0	0 RADIATOR MOB 88897 3B	/
EJ01 BHH1620	4CI02	1	0	0	0 ENG MNTG BRK 88897 20B	/
EJ01 AHH6489	4DC03	1	0	0	0 O/RIDER RH R 88897 6B	/

END OF CUSTOMER Queries to JAS Entered by JAS Nt Wght 10615gms

879950

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: MOSS U.K.	To: JIM.	
From: ERIK.	Date: 28 Sept 98	No. Pages: 1.

Ref: E.J.01.

Please supply the following.

RESTRAINING CHIP 17H7990B x 4.
SPASH SHIELD R.H. HZA 4304 x 1. ✓
REAR HARNESS 543-BMH 1739 x 1. — R.D.C.
LATE RADIATOR. NRP 1154 x 1 ✓
REAR LAMP. BHA 4175 x 2.
DISTANCE PIECE AHH 6216 x 6. ✓
PLATE AHH 7334 x 4. ✓
SPRING SHACKLE KIT AHH 5018k x 2. ✓
R.H. REAR OVER. RIDER. AHH 6489 x 1. ✓
FRONT SIDE LAMP. BHA 4966 x 1.
REAR BUMP STOP. RUBBERS. AHH 9158 x 2. ✓
BONNET CABLE AHH 6426B x 1.
THRATTLE CABLE AHH 8462 x 1.
DOOR LOCK PAIR BHM 973B x 1.
972/

cont'd.

MGB

strip out engine bay & repaint fittings \$550

spot welding, sea etc, star clip

body door,

strip, bay \$2000

3/ dollar cost + $\sqrt{118}$ = 40 hrs

→ \$2000

~~SC1202/RLD~~

~~RT-1202/CLD~~

SC1274

GASKET.

BHH 972G x 2. ✓

CLIP.

37H 3387 x 2. ✓

CALIPER PISTON

8G8642 x 4. ✓

SEAL KIT.

GRK5007 x 1 ✓

CALIPER BOOTS

ATB 6076 x 4. ✓

✓

PS 610241 x 4. ✓

Hopefully for our van, (i.e.
your van.) tomorrow.

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number 01293 512374

Shle-

MOSS

HZA 5321	L.H. R.H. wheel arch reinforcement X 2.
HZA 615	R.H. wheel arch outer
HZA 138	L.H. " " "
BMH 9005	L.H. rear spring mounting
BMH 9004	R.H. " " "
HZA 496	R.H. outer sill
HZA 497	L.H. " "
HZA 238	R.H. castor sector
HZA 239	L.H. " "
HZA 303	L.H. buffer plate extension
HZA 302	R.H. " " "
MB52 L	L.H. buffer plate mounting bracket
MB52 R	R.H. " " "
HZA 592	front valance.
MB 11	
ARH 218 Z	front grill

Sent to the FARM WORKSHOP on
daily van, under S.C. ref. HUMWOOD
Enk's MGB

KINMAN

HZA 3843

L.H. front wing

HZA 3842

R.H. " "

HZA 4226

R.H. rear wing

HZA 4225

L.H. " "

SC STOCK

HZA 5509

L.H. door

HZA 5508

R.H. door

HZA 628

R.H. floor pan

HZA 629

L.H. floor pan

HZA 188

lower sill - R.H.

HZA 189

" " L.H.

HZA 231B

Jacky part x 2

HZA 492B

" " reinforcement x 2

HZA 260

R.H. sill end

HZA 261

L.H. " "

BFP 38

jacky part to add repair repair x 2

DEPOT 10

ADMINISTRATIEBEWIJS (C1)

voor vervoerder

afzender

KLANTNR 1460600
KIMMAN HAARLEM BV
SCHIPHOLWEG 5
2034 LS HAARLEM

aan

SC PARTS
UK

comp.nr afz. frankeringsvoorschrift

code 1e verv. per

code 2e verv. verder per

FRANKO

BEENTJES VVZ HAARLEM
TEL: 023-5319399

merken en/of nrs

aantal

verpakking

inhoud (soort der goederen)

bruto gew. in kg

2 fut wings

2 ncan wings

100 190551

tot. aantal colli

4

totaal bruto gew.

100

plaats van afzending

HAARLEM

datum

VAK 452189



auteursrecht:
stichting vervoeradres,
den haag

aantekeningen vervoerder

ADMINISTRATIE-
BEWIJS (C2)

voor vervoerder

afzender

KLANTNR 1460600
KIMMAN HAARLEM
SCHIPHOLWEG 5
2034 LS HAARLEM

aan

SC
PARTS
UK

comp.nr afz. frankeringsvoorschrift

code 1e verv. per

code 2e verv. verder per

FRANKO

BEENTJES

VERDER PER

023-5319399

FRANKO

bev. code

netto vr.

omz.bel.

vr.

vracht

ONGEFR.

bev. code

vr. 1e v.

vr. 2e v.

vr. 3e v.

toeslag

totaal

paraaf vertrek

paraaf aankom

aantal colli

4

gewicht

inhoud

datum

VAK 452189

TOTAAL ONDERDELEN

PACKING COSTS

2099.55

21.25

TOTAAL DIVERSEN

21.25

ALL PARTS ORIGIN FROM UK
SEPARATE PACKED
CONFIRM YR ORDER : REF AJ
FREIGHTNOTE 452189

TRANSPORTEREN DIVERSEN

21.25

Schipholweg 5
Postbus 192
2000 AD Haarlem
Tel. 023 - 5339069
Fax 023 - 5362381

ART. 1550 UITGAVE: B.V. BEURTVAAK HAARLEM
TEL. 070 - 306 67 66 - AUTOMATISCHE BESTELLIJN 070 - 306 67 89



17197 SC PARTS GROUP LTD
 t.a.v. VAT GB 217 0502 08
 13 COBHAM WAY GATWICK ROAD
 CRAWLEY WEST SUSSEX RH102RX UK

B A L I E F A K T U U R

opdrachtnummer : 518601


fakturenummer : 190551
 faktuurdatum : 16-12-97

aantal	artikelnummer	omschrijving	stuksprijs	bedrag
1	HZA 3842	FRONT WING	977.08 50.00 %	488.55
1	HZA 3843	FRONT WING	977.08 50.00 %	488.54
1	HZA 4224	PLAAT CPLT, SPAT	1058.92 47.00 %	561.23
1	HZA 4225	PLAAT CPLT, SPAT	1058.92 47.00 %	561.23
TOTAAL ONDERDELEN				2099.55
PACKING COSTS				21.25
TOTAAL DIVERSEN				21.25
ALL PARTS ORIGIN FROM UK SEPARATE PACKED CONFIRM YR ORDER : REF AJ FREIGHTNOTE 452189				
TRANSPORTEREN DIVERSEN				21.25

Schipholweg 5
 Postbus 192
 2000 AD Haarlem
 Tel. 023 - 5339069
 Fax 023 - 5362381

Op al onze transacties zijn de BOVAG-standaardbepalingen van toepassing, waarover overeenstemming is bereikt met de ANWB en de Consumentenbond. Deze BOVAG-standaardbepalingen kunt u inzien bij ons bedrijf en gratis meenemen.

Bank: ABN•AMRO nr. 44.73.16.222
 Postbank nr. 30611
 K.v.K. Haarlem nr. 44430



SC Parts Group Ltd

13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
 Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
 Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number 01293 546570

Destination: Moss Europe To: Jim Cassim		From: Erik Jeffery
Date: 22nd December, 1997		No. Pages: 1

Dear Jim,

Thanks for sorting out the parts for my MGB.

Can you send a few others please.

HZA 5320	x	1	(I ordered 2 of the same side)
HZA 236A	x	1	
HZA 237A	x	1	
HZA 268	x	1	
HZA 269	x	1	

Can you try and find an HZA 239 and HZA 615 if possible.

All to be charged to our account and sent to THE FARM WORKSHOP
 in Hillingdon on your VAN.

Thank you very much and a Merry Christmas.

Erik

P.S. See what you can do for a disk please.

*Futures to you telephone call
 a 2 spec HZA 239 will be o.k.*

headlamp - wiper without side lamp x 2
 " " " x 2
 " " " x 2
 " " " x 2
 BHA 1966 sublamp x 2 \$10.75
 -57 W5354 (for lens) x 2 \$2.65
 -57 W5355 bezel (or other) x 2 \$6.75
 57 W5358 lamp socket gasket x 2 \$0.30
 BHA L283 in photo lamp x 2 \$7.50
 " " " x 2 SC
 BHA 13 radio speaker cable \$10.75
 H2A 612 det panel cable 5/L BERT
 AKS 5155 det cord HL \$25.25 ?
 AHA 61035GT body molding - BERT \$16.25
 - GHF 1135 nuts 36 \$0.7
 - BHA 6360 studs 6 \$0.20
 BHA 2049 gear box gasket x1 \$1.45
 BHA 9500 sand board kit x1 - det. \$20.00
 AHC 187 g/water tray \$4.00
 SG 604083 x1 det \$0.26
 SG 604103 x3 \$0.27


supplies

SPECIAL DOOR PANELS


For those with new British Motor Heritage Ltd. bodysells which obviously have the late style doors fitted with keyhole adapters for door panel attachment, we can offer you door panels with the 1968-71 styling to fit these doors. This also applies to Customers who have purchased the new doors for renovation purposes on old bodysells.

Listed below are the part numbers for these door panels and also 6 piece panel kits. We also offer leather covered trim panels, but we would ask you to contact us first to discuss this subject as there are various recommendations that we can make before you order these parts.

DOOR PANELS



6 PIECE TRIM KITS



PART NO	DESCRIPTION
DP119	PAIR OF DOOR PANELS
TK121	6 PIECE PANEL KIT-ROADSTER
TK122	6 PIECE PANEL KIT-GT

CODE	COLOURS AVAILABLE
AA	BLACK/BLACK
AB	BLACK/BLUE
AM	BLACK/RED
AV	BLACK/WHITE
BB	BLUE/BLUE
MA	RED/BLACK
MW	RED/WHITE

PANELS

PART NO	DESCRIPTION	HL	RETAIL	disc	NETT
HZA409 etc	FRONT WING MGB	98.00	17.5		163.35
HZA4224/5	REAR WING MGB	37.00	40.0		202.20
HZA5000/1	REAR WING R/B	33.00	40.0		199.80
HZA4222/3	REAR WING GT	405.00	40.0		243.00
HZA4904/5	REAR WING R/B	405.00	40.0		243.00
HZA4014	BONNET MGB	78.00	36.0		113.90
HZA5511	BOOT LID MGB	35.00	36.0		86.40
HZA5508 etc	DOOR MGB/GT	78.00	36.0		113.90*
HZA496/7	SILL	2.00	20.0		25.60
AHH6285	LOOM SUPPORT			0.75	
AHH6287	LOOM SUPPORT			0.75	
AHC60	LOOM SUPPORT			0.75	
ALK3268	NUMBER PLATE BACK				3.25
AHA5791	NUMBER PLATE BACK				3.25
THESE PLATES ABOVE ARE POWDER COATED NOT JUST PRIMED					
CZJ279 etc	WING MIDGET	505.00	30.0		143.50
CZJ704	BONNET MIDGET	747.00	17.5		203.80
CZJ565	FRONT VAL MIDGET	92.00	25.0		144.00
AHA5552/3 etc	SILL MIDGET	48.00	20.0		38.40
CZJ694/5	SILL MIDGET	48.00	20.0		38.40
AHA9925	GRILLE MIDGET	42.00	40.0		61.20
AHH6380/1	ROADSTER	0.00	30.0		49.00
AHH7415/6	GT	0.00/64.00	30.0		49.00/44.80

1.1.1998
 * 106 :
 205

CONVERSION KIT MGB/GT RUBBER TO CHROME BUMPER

102.
30

72.50

Non standard parts

- 2 Modified front bumper irons nuts bolts and washers
- 2 Rear bumper mounting studs nuts washers and spacers
- 2 Rear wing extensions - under lamp panels - require welding
- 2 Modified rear bumper irons
- 1 Standard front valence with additional cut-outs

} 110 SINGLES
|
| 102 105

Optional

- 2 Front wing infils - used when original wings retained (These need to be welded in place)

Standard parts

- 1 Front bumper and fitting kit
- 1 Grille - your choice chrome slatted / honeycombe / recessed
- 3 Grille brackets and fitting kit
- 2 Side / indicator lamps nuts and washers
- 1 Rear bumper and fitting kit
- 2 Rear bumper infil finishers and rivets
- 4 Overriders - your choice all chrome or rubber faced
- 2 Number plate brackets screws and fittings
- 2 Number plate lamps plinths chrome screws and nuts
- 1 Front valence bolt kit

SPECIAL SHOW PRICE £495

Please do not confuse this kit with others that lack ALL the parts you require.

Modifications required :-

Front rubber bumper mounting is cut back to radiator tray level to allow grille installation, modified bumper irons locate off of the remaining lower portion of the mounting below radiator tray level and 10mm holes are drilled accordingly. At the rear 2 x 13mm holes must be drilled at the outer edge of the reinforcing plates for the rubber bumper mountings at an appropriate height.

M.G.Services Heathrow
0044 (0)1753 880267 Tel + fax

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570

Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail Engineering and complete product development facilities • British Motor Heritage approved

PURCHASE ORDER

To : Jim / Moss Evans

F.A.O. : SALES

Date : 18/12/97

Order ref. : EJ100

Please supply the following :-

HZA 5321 x2

MB 52L

HZA 615

MB 52R

HZA 138

MB 11

BMH 9005

ARH 2182

BMH 9004

HZA 496

CHARGE TO S.C. ACCT.

HZA 497

DELIVER VIA YOUR VAN

HZA 238

TO FARM WORKSHOP.

HZA 239

HZA 302

HILLINGDON

HZA 303

Many Thanks

Dave Woodberry

HZA 260 - R.H. side end ✓ stable

HZA 261 - L.H. " " ✓ "

BPP 38 jacking part to cross member
seperti panel. X 2 ✓ stable

HZA 303 L.H. baffle plate extension X


HZA 302 R.H. " " " " X

BPP 06A - MB52L L.H. baffle plate mounting bracket X

BPP 07A - MB52R R.H. baffle plate " " X

HZA 592 - front valance - MB11.

RM 218B



MGB ^{rooster}

HZA ~~4832~~ ³⁸⁴³ L.H. front wing. ✓ NOT SPAN.

HZA ~~4833~~ ³⁸⁴² R.H. " " ✓

HZA ~~5000~~ ⁴²²⁴ - R.H. rear ✓ ~~Heritage~~ NOT SPAN

HZA ~~5001~~ ⁴²²⁵ - L.H. " " ✓

HZA 5509 - L.H. door ✓ slats

HZA 5508 R.H. door. ✓ "

HZA 5321 - front R.H. wheel arch reinforcement x

HZA 5321 - front L.H. " " " " x

HZA 615 - R.H. wheel arch outer x

HZA 138 - L.H. " " " " x

HZA 628 - R.H. floor pan ✓ slats

HZA 629 - L.H. floor pan ✓ "

BMA 9005 L.H. rear spring hanger - front x

BMA 9004 R.H. " " " " - " x

HZA 497 - L.H. outer sill x ~~NOT SPAN~~

HZA 496 - R.H. " " " " x

HZA 188 - RH ← sill drag pan inner sill ✓ slats

HZA 189 - L.H. " " " " ✓ "

HZA 239 - L.H. cattle seat x

HZA 238 - R.H. " " " " x 2 ✓ slats

HZA 2310 - Jack pan reinforcement x 2 ✓ slats

HZA 4920 - " " " " x 2 ✓ slats

MGB

- HZA 297 L.H. outer sill - MB 48 L
- HZA 496 R.H. " " - MB 48 R
- HZA 188 R.H. sill clay pan slab
- HZA 189 L.H. " " "
- HZA 239 L.H. castle section
- HZA 238 R.H. " " "
- HZA 231B Jockey part re-entrant x 2. - slab
- HZA 492B Jockey part " x 2. - slab
- HZA 615 rear wheel and axle - LH
- HZA 138 " " " " - R.H.
- HZA 5508 - R.H. door jam.
- HZA 5001 gear ing 2.H

SC Parts Group Ltd



13 Cobham Way Gatwick Road Crawley West Sussex RH10 2RX England Tel 01293 547841 Fax 01293 546570
 Austin Healey, Jaguar and Range Rover Specialists • Over twenty years as manufacturers and suppliers of parts worldwide • Wholesale and retail
 Engineering and complete product development facilities • British Motor Heritage approved

FAX TRANSMISSION

If you do not receive the full transmission, contact fax number **01293 546570**

Destination: <u>JEFFERY MG.</u>	To: <u>RON or SPK-1</u>
From: <u>SPK.</u>	Date: <u>9 Oct</u>
	No. Pages: <u>2</u>

Together with our order for collection Monday,
 Can you please supply the following.

- | | | |
|------------|-------------|-----------|
| CLIP | 17H 7990B | X 4. |
| LAMP-REAR | BHA 4175 | X 2. |
| LAMP-FRONT | BHA 4966 | X 1. |
| CABLE | AHH 6426B | X 1 |
| CABLE | AHH 8462 | X 1. |
| DOOR JACK | BHH 972/973 | X 1 pair. |
| TUBE | AHH 6162 | X 2 |
| JX. RUBBER | GFX 7204 | X 1 |
| " " | GFX 7493 | X 2 |
| DECAL KIT | MGK 2012 | X 1 |
| BUFFER | IG8782 | X 2 |
| BUSH | AHH 7854 | X 2 |