

Check MOT history

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX? vrm=MUF718F&make_result=MERCEDES-BENZ&model_result=SL&mot_first_used_date=1999-10-27&vehicle_age=8590&mot_expiry_date=2024-04-</u>

<u>27&mot expiry date days left=359&user satisfaction banner=0&vehicle data origin=MTS&vehicle type=LGV)</u> to help us improve.

< Back

MUF 718F

MERCEDES-BENZ SL

Check another vehicle (/)

Colour

Blue

Fuel type

Petrol

Date registered

27 October 1999

MOT valid until

27 April 2024

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-v5c?registration=MUF718F)

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA (https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes)</u>.

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

Hide

Date tested **28 April 2023**

PASS

Mileage

44,692 miles

Test location

View test location

MOT test number

1024 9218 0674

Expiry date

27 April 2024

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))
- What are advisories?

Date tested

19 April 2023



Mileage

44,692 miles

Test location

View test location

MOT test number

8465 7081 2283

Repair immediately (major defects):

- Front Windscreen washer not working (3.5 (a))
- Offside Front Service brake excessively binding (1.2.1 (f))
- Nearside Rear Service brake excessively binding (1.2.1 (f))
- Brake performance unable to be tested due to brakes badly binding (1.2.1 (g))

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))
- What are defects and advisories?

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested

8 May 2017

PASS

Mileage

44,472 miles

Test location

View test location

MOT test number

9024 1725 3643

Expiry date

7 May 2018

Advisory notice item(s)

- Oil leak
- Offside Rear wheel bearing has slight play (2.6.2)
- Front wheel bearing has slight play (2.5.A.3c)
- · Slight play in front suspension lower trunions
- What are advisories?

Date tested

5 May 2016

PASS

Mileage

44,285 miles

Test location

View test location

MOT test number

6956 7292 2693

Expiry date

4 May 2017

Advisory notice item(s)

- oil leak
- play in nearside and offside front trunnion pins
- suspect offside headlamp incorrect
- ▶ What are advisories?

Date tested

3 May 2016

FAIL

Mileage

44,278 miles

Test location

View test location

MOT test number

4326 2354 9783

Reason(s) for failure

- Windscreen washer provides insufficient washer liquid (8.2.3)
- Steering component mounting prescribed area is excessively corroded (2.2.C.1h)

Advisory notice item(s)

- oil leak
- play in nearside and offside front trunnion pins
- suspect offside headlamp incorrect
- What are failures and advisories?

Date tested

23 December 2014

PASS

Mileage

43,824 miles

Test location

View test location

MOT test number

5394 1775 4342

Expiry date

22 December 2015

Date tested

23 December 2014

FAIL

Mileage

43,824 miles

Test location

View test location

MOT test number

5370 2775 4390

Reason(s) for failure

- Nearside Headlamp aim too low (1.8)
- Offside Headlamp aim too low (1.8)
- What are failures?

Date tested

26 July 2013

FAIL

Mileage

43,824 miles

Test location

View test location

MOT test number

3155 5760 3276

Reason(s) for failure

- Nearside Headlamp aim too low (1.8)
- Offside Headlamp aim too low (1.8)
- Nearside Rear Lower Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

• Offside Rear Lower Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

Advisory notice item(s)

- · Non obligatory mirror damaged
- · front tyres perished and have minor age related cracks in the tread...
- · rear lower suspension arm bushes perished..
- What are failures and advisories?

Date tested

8 June 2010



Mileage

41,590 miles

Test location

View test location

MOT test number

5109 4975 0158

Expiry date

7 June 2011

Date tested

1 June 2009



Mileage

40,404 miles

Test location

View test location

MOT test number

1845 8265 9125

Reason(s) for failure

- Windscreen washer provides insufficient washer liquid (8.2.3)
- What are failures?

Date tested

1 June 2009

PASS

Mileage

40,404 miles

Test location

View test location

MOT test number 4945 4265 9143

7373 7203 3 I

Expiry date 31 May 2010

Date tested 15 May 2008

PASS

Mileage 38,750 miles

Test location

▶ View test location

MOT test number **5725 3663 8133**

Expiry date 14 May 2009

Date tested 11 May 2007

PASS

Mileage 34,661 miles

Test location

View test location

MOT test number 6812 4103 7136

Expiry date

10 May 2008

Date tested 10 May 2006

PASS

Mileage 30,841 miles

Test location

View test location

MOT test number

1222 0083 6165

Expiry date

9 May 2007

Check for vehicle recalls

See if MERCEDES-BENZ SL MUF718F has outstanding recalls



<u>Cookies Terms and conditions Privacy notice Accessibility statement MOT history API Service status</u>

Built by the **Driver & Vehicle Standards Agency**

OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated

