Check MOT history

This is a new service – <u>Complete a quick survey (https://www.smartsurvey.co.uk/s/GIZZX?</u> <u>vrm=D139JMK&make result=CITROEN&model result=2CV&mot first used date=1986-12-</u> <u>31&vehicle age=13398&mot expiry date=2023-10-</u> <u>12&mot_expiry_date_days_left=36&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV)</u>

to help us improve.

< <u>Back</u>

DI39 JMK CITROEN 2CV

Check another vehicle (/)

Colour Grey

Fuel type Petrol

Date registered 31 December 1986

MOT valid until

12 October 2023

Get an MOT reminder (https://www.gov.uk/mot-reminder) by email or text.

Download test certificates (/enter-v5c?registration=D139JMK)

If you think the MOT expiry date or any of the vehicle details are wrong: <u>contact DVSA</u> (<u>https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes</u>).

Show all sections

MOT history

Check mileage recorded at test, expiry date, and test outcome

• Hide

Date tested 10 October 2022

PASS Mileage 51,565 miles

View test location

MOT test number 8427 5995 5026

Expiry date 12 October 2023

Date tested 13 October 2021



Mileage 51,135 miles

Test location

View test location

MOT test number **1443 4113 0269**

Expiry date 12 October 2022

Monitor and repair if necessary (advisories):

- Nearside Front Suspension component pin or bush slightly worn axle (5.3.4 (a) (i))
- Offside Front Suspension component pin or bush slightly worn axle (5.3.4 (a) (i))
- Nearside Front Outer Track rod end modified, but not inappropriately (2.1.3 (f) (i))

What are advisories?

Date tested 13 October 2021

FAIL

Mileage 51,135 miles

Test location

View test location

MOT test number 9847 7063 7090

Repair immediately (major defects):

- Offside Headlamp aim too low (4.1.2 (a))
- Nearside Headlamp aim too low (4.1.2 (a))

Monitor and repair if necessary (advisories):

- Nearside Front Suspension component pin or bush slightly worn axle (5.3.4 (a) (i))
- Offside Front Suspension component pin or bush slightly worn axle (5.3.4 (a) (i))
- Nearside Front Outer Track rod end modified, but not inappropriately (2.1.3 (f) (i))
- What are defects and advisories?

Date tested 12 October 2020

PASS Mileage

50,621 miles

Test location

View test location

MOT test number 5662 1180 3602

Expiry date 11 October 2021

Repair as soon as possible (minor defects):

• Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt both sides (2.1.3 (g) (i))

Monitor and repair if necessary (advisories):

- Nearside Front Play in steering rack inner joint(s)
- What are advisories?

Date tested 10 April 2019

PASS

Mileage 49,163 miles

Test location

View test location

MOT test number 6745 2926 5257

Expiry date 9 October 2020

Repair as soon as possible (minor defects):

- Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Monitor and repair if necessary (advisories):

- Slight play in steering rack inner joints n/s and o/s
- Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- What are advisories?

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. <u>Find</u> <u>out more (https://www.gov.uk/government/news/mot-changes-20-may-2018)</u>.

Date tested 28 August 2013



Mileage 49,073 miles

Test location

View test location

MOT test number **5653 9044 3258**

Expiry date **27 August 2014**

Advisory notice item(s)

- Offside Front Seat belt stitching slightly frayed (5.2.2b)
- transmission noise
- Play in steering rack inner joint(s)
- What are advisories?

Date tested 8 August 2013



Mileage 49,073 miles

Test location

View test location

MOT test number 9474 1012 3232

Reason(s) for failure

- Parking brake: efficiency below requirements (3.7.B.7) **DANGEROUS**
- Offside Front Headlamp aim too high (1.8)
- Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Advisory notice item(s)

- Offside Front Seat belt stitching slightly frayed (5.2.2b)
- Play in steering rack inner joint(s)
- Transmission noise
- What are failures and advisories?

Date tested 28 May 2010



Mileage 48,903 miles

Test location

View test location

MOT test number 2429 4854 0419

Expiry date **27 May 2011**

Advisory notice item(s)

- Offside Axle king pin has slight play in pin and/or bush (2.5.A.3a)
- Exhaust has part of the system slightly deteriorated (7.1.1a)
- Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- · Nearside outer track rod end joint cover split/missing
- Offside outer track rod end joint cover split/missing

What are advisories?

Date tested 16 September 2009



Mileage 48,814 miles

Test location

View test location

MOT test number **3937 0935 9240**

Expiry date **25 September 2010**

Advisory notice item(s)

- Exhaust has part of the system slightly deteriorated (7.1.1a)
- Rear Brake pipe slightly corroded (3.6.B.2c)
- Nearside Axle king pin has slight play in pin and/or bush (2.5.A.3a)
- Offside Axle king pin has slight play in pin and/or bush (2.5.A.3a)
- Oil leak

Date tested 26 September 2008



Mileage 48,736 miles

Test location

View test location

MOT test number 3442 2077 8241

Expiry date 25 September 2009

Advisory notice item(s)

- Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Nearside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)
- Offside Front Axle king pin has slight play in pin and/or bush (2.5.A.3a)
- Oil leak
- What are advisories?

Date tested 20 September 2007



Mileage 48,345 miles

Test location

View test location

MOT test number 6234 4376 7286

Reason(s) for failure

Parking brake lever has no reserve travel (3.1.6b)

What are failures?

Date tested **20 September 2007**



Test location

<u>View test location</u>
 MOT test number
 8031 6306 7206

Expiry date 19 September 2008

Date tested
8 August 2006



Mileage 48,124 miles

Test location

View test location

MOT test number 6125 8032 6287

Expiry date 7 August 2007

Check for vehicle recalls

See if CITROEN 2CV D139JMK has outstanding recalls

✓ Show

<u>Cookies</u> <u>Terms and conditions</u> <u>Privacy notice</u> <u>Accessibility statement</u> <u>MOT history API</u> <u>Service status</u>

Built by the Driver & Vehicle Standards Agency

OGL

All content is available under the <u>Open Government Licence v3.0</u>, except where otherwise stated



© Crown copyright