

BMS Surrey
 201-205
 Kingston Road
 Leatherhead
 Surrey
 KT22 7PB
 VAT Reg No:172 2375 17



Mr Sanjay Berry
 18 Ridgeway
 Epsom BMW Z1
 Surrey G414 YYT
 KT19 8LB Mil: 58505

1826
 25/02/2015

VAT Reg No:

MRSANJAY

Quantity	Details	Unit Price	Disc Amt	Net Amt	VAT %	VAT
1.00	Speedometer	377.17	0.00	377.17	20.00	75.43
1.00	Fit supplied instrument cluster printed circuit board	0.00	0.00	0.00	20.00	0.00
1.00	Diagnose speedo not working, replace speedo and printed circuit board	90.00	0.00	90.00	20.00	18.00
1.00	Old speedo replaced at 58505 miles as faulty with new speedo, part number: 6212297108	0.00	0.00	0.00	20.00	0.00

Total	0.00
Total Net Amount	467.17
Carriage Net	0.00
Total VAT Amount	93.43
Invoice Total	560.60