



Porsche Centre Sheffield  
 Sheffield Road  
 Meadowhall  
 Sheffield  
 S9 2FZ  
 0114 256 4455  
 service@porschesheffield.co.uk  
 www.jct600.co.uk

Please Note THIS IS  
 NOT AN INVOICE

VHC Date 08/11/2023  
 Make Porsche  
 Model 981 Cayman  
 Reg No. YR13XNH  
 Mileage 30017  
 Job Card No. 43565

Video Arrival	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Video				Video	0.00	0.00	No			
Inside Vehicle	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Horn Operation					0.00	0.00	No			
Wipers Operation					0.00	0.00	No			
Washers Operation					0.00	0.00	No			
Instrument Operation					0.00	0.00	No			
Seat Belt Operation					0.00	0.00	No			
Under bonnet	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Brake Fluid Condition					0.00	0.00	No			
Battery Condition					0.00	0.00	No			
Coolant Condition					0.00	0.00	No			
Engine Oil Level/Leaks					0.00	0.00	No			
Power Steering Fluid					0.00	0.00	No			
V Belt Condition					0.00	0.00	No			
Wheels & Tyres	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
								Depths(mm) Outer Middle Inner		
N/S Front Tyre				(PIRELLI 235, 35, 20 88, N1)	5.5	5.8	5.2	0.00	0.00	No
O/S Front Tyre				(PIRELLI 235, 35, 20 88, N1)	5.8	6.1	5.5	0.00	0.00	No
N/S Rear Tyre				(PIRELLI 265, 35, 20 88, N1)	4.8	4.8	4.9	0.00	0.00	No
O/S Rear Tyre				(PIRELLI 265, 35, 20 88, N1)	4.7	5.2	5.1	0.00	0.00	No
Wheels					0.00	0.00		0.00	0.00	No
Spare Tyre					0.00	0.00		0.00	0.00	No
Spacesaver/Puncture Repair Kit					0.00	0.00		0.00	0.00	No
Locking Wheel Nut					0.00	0.00		0.00	0.00	No
Geometry					0.00	0.00		0.00	0.00	No
Lighting	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Front Operation/Condition					0.00	0.00		0.00	0.00	No
Rear Operation/Condition					0.00	0.00		0.00	0.00	No
Brakes & Hubs	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Front Pads					0.00	0.00		0.00	0.00	No
Front Brake Disc					0.00	0.00		0.00	0.00	No
Rear Pads					0.00	0.00		0.00	0.00	No
Rear Brake Disc					0.00	0.00		0.00	0.00	No
Handbrake Condition					0.00	0.00		0.00	0.00	No
Brake Hydraulic System					0.00	0.00		0.00	0.00	No
External Inspection	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Front Wipers					0.00	0.00		0.00	0.00	No
Rear Wiper					0.00	0.00		0.00	0.00	No
Windscreen					0.00	0.00		0.00	0.00	No
Underside	Green	Amber	Red	Report & Recommendations	Identified (£)	Authorised (£)	Auth			
Steering Wear					0.00	0.00		0.00	0.00	No
Front Suspension					0.00	0.00		0.00	0.00	No

This report is the result of a visual examination only of those items listed. Further checks may be necessary to determine the full extent of requirements.

Rear Suspension					0.00	0.00	No
Driveshafts/Leaks					0.00	0.00	No
Exhaust System/Catalyst					0.00	0.00	No
<b>Additional Notes</b>	<b>Green</b>	<b>Amber</b>	<b>Red</b>	<b>Report &amp; Recommendations</b>	<b>Identified (£)</b>	<b>Authorised (£)</b>	<b>Auth</b>
Additional Note 1					0.00	0.00	No
Additional Note 2					0.00	0.00	No
Additional Note 3					0.00	0.00	No
Additional Note 4					0.00	0.00	No
Additional Note 5					0.00	0.00	No
Additional Note 6					0.00	0.00	No
Additional Note 7					0.00	0.00	No
<b>Video Overview</b>	<b>Green</b>	<b>Amber</b>	<b>Red</b>	<b>Report &amp; Recommendations</b>	<b>Identified (£)</b>	<b>Authorised (£)</b>	<b>Auth</b>
Video Overview					0.00	0.00	No
					<b>Total Identified (£)</b>	<b>Total Authorised (£)</b>	
					0.00	0.00	

#### Additional Items Details

Additional Items	Mandatory	PartNo	Quantity	Unit Price (£)	VATRate (£)	Price(Inc.Vat) (£)	Auth
	<input type="checkbox"/>		0	0	0	0	<input type="checkbox"/>