

Dealer Service History

VIN: WP0ZZZ99ZDS115800

2013 911 Carrera 4S (991-421)

Total Warranty Repair Days: 29 Total Number of Jobs: 16

Service Job #1 - Porsche Group Operations Centre

Service Dates: April 10, 2013 - April 18, 2013

Odometer Value: 11 Miles Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|------------------------|-------------|--------------|
| Entire vehicle – General | Technical inspection § | PDI & VTS | |

Service Job #2 - Porsche Centre Colchester

Service Dates: October 13, 2014 - October 14, 2014

Odometer Value: 4,398 Miles

Breakdown Status: No

Services Performed

| Location | Symptom | Information | Warranty Use |
|--|-------------------|-------------|--------------|
| Replace vent line | Workshop campaign | | ✓ |
| Re-program rear-end electronics control unit | Workshop campaign | | ✓ |
| Code instrument cluster | Workshop campaign | | ✓ |
| Re-program instrument cluster | Workshop campaign | | ✓ |
| Cover for door arrester | Workshop campaign | | ✓ |
| Filler flap switching element | No function | | ✓ |

Service Job #3 - Porsche Centre Colchester

Service Dates: April 24, 2015 - April 28, 2015

Odometer Value: 5,340 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|----------------------------------|-------------------|---|--------------|
| Replace engine compartment cover | Workshop campaign | | |
| Entire vehicle – General | Minor maintenance | Intermediate Service & BRake Fluid Change | |

Service Job #4 - Porsche Centre Colchester

Service Dates: May 31, 2016 - May 31, 2016

Odometer Value: 5,340 Miles

Breakdown Status: No

Services Performed

| Location | Symptom | Information | Warranty Use |
|-----------------------------|--|-------------|--------------|
| Entire vehicle – General | General workshop visit / Service (DMS) | | |

Service Job #5 - Porsche Centre Colchester

Service Dates: May 31, 2016 - May 31, 2016

Odometer Value: 5,340 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|--|-------------|--------------|
| Entire vehicle – General | General workshop visit / Service (DMS) | | |

Service Job #6 - Porsche Group Operations Centre

Service Dates: November 2, 2016 - November 10, 2016

Odometer Value: 10,420 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|----------------------------------|------------------------|---|--------------|
| Wheel | Imbalance | | |
| Entire vehicle – General | Technical inspection § | 111 point check. | |
| Entire vehicle – General | Other | Replace centre caps. Remove washer bottle clear out gunky fluid, re fit washer bottle + re fill fluid. Replace tool kit holder. Replace plates. Trim repair to rear 1/4 trim. Charge + test battery. Boot floor repair + touch up. 2 VTS cards supply + code. | |
| Entire vehicle – General | Other | Replace A/c control panel + code. Investigate coolant switch over valve short circuit fault, carry out vacuum test on system tester, system tight, Check feeds at vacuum valve, valve found to be faulty, replaced vacuum valve, tested all ok. | |
| Replace engine compartment cover | Workshop campaign | | • |

Service Job #7 - Porsche Centre West London

Service Dates: May 22, 2017 - May 23, 2017

Odometer Value: 13,581 Miles

Breakdown Status: No

Services Performed

| Location | Symptom | Information | Warranty Use |
|-----------------------------|-------------------|---|--------------|
| Entire vehicle – General | Major maintenance | Carry out 40,000 mile service and brake fluid change | |

Service Job #8 - Porsche Centre West London

Service Dates: August 16, 2018 - August 17, 2018

Odometer Value: 22,162 Miles

Breakdown Status: Yes

Services Performed

| Location | Symptom | Information | Warranty Use |
|------------------|--------------------------------|-------------|--------------|
| VTS control unit | Switching off/on automatically | | ✓ |
| Right condenser | Leaks | | ✓ |

Service Job #9 - Porsche Centre West London

Service Dates: December 19, 2018 - December 21, 2018

Odometer Value: 23,291 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|---|--------------------------------------|--------------|
| Entire vehicle – General | Warranty check for pre-owned Porsche vehicles | Carry out Porsche 111 point check | |

Service Job #10 - Porsche Centre West London

Service Dates: December 28, 2018 - December 28, 2018

Odometer Value: 23,324 Miles

Breakdown Status: No

Services Performed

| Location | Symptom | Information | Warranty Use |
|----------|-------------|-------------|--------------|
| Horn | No function | | ✓ |

Service Job #11 - Porsche Centre West London

Service Dates: April 30, 2019 - April 30, 2019

Odometer Value: 24,276 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|-------------------|--|--------------|
| Left condenser | Leaks | | ✓ |
| Entire vehicle – General | Other | Carry out Mot Test | |
| Entire vehicle – General | Minor maintenance | Carry Out 60,000 Mile Porsche Maintenance Service Carry Out Status Condition Report Brake fluid change | |

Service Job #12 - Porsche Centre Guildford

Service Dates: November 19, 2021 - November 29, 2021

Odometer Value: 48,674 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|------------------------|---------------|--------------|
| Entire vehicle – General | Technical inspection § | Carry out MOT | |
| Retrofit heat shield | Workshop campaign | | ✓ |
| On board diagnostic | Electrical faults | | |

Service Job #13 - Porsche Centre Guildford

Service Dates: December 1, 2021 - December 1, 2021

Odometer Value: 49,047 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|---|---|--------------|
| Entire vehicle – General | Major maintenance | carry out major service, bfc, spark plugs, drive belt check, mounts check | |
| Gas spring rear | Permeable to gas/exhaust gas | | |
| Entire vehicle – General | Warranty check for pre-owned Porsche vehicles | 111 point check | |
| Brake pad rear | Severe wear | | |
| Entire vehicle – General | Other | carry out ac service | |
| Wiper blade | Severe wear | | |
| Entire vehicle – General | Other | carry out geometry | |
| Brake pad front | Severe wear | | |
| Entire vehicle – General | Other | replace number plates | |
| Cover molding | Loosely fitted | | |

Service Job #14 - Porsche Centre Guildford

Service Dates: March 13, 2023 - March 17, 2023

Odometer Value: 50,661 Miles

Breakdown Status: No

Services Performed

| Location | Symptom | Information | Warranty Use |
|-----------------------------|------------------------------|-------------|--------------|
| Boot CV joint | Permeable to oil/grease | | ✓ |
| Entire vehicle – General | Technical inspection § | мот | |
| Gas spring front | Permeable to gas/exhaust gas | | ✓ |

Service Job #15 - Porsche Centre Guildford

Service Dates: July 10, 2024 - July 10, 2024

Odometer Value: 52,760 Miles

Breakdown Status: No

| Location | Symptom | Information | Warranty Use |
|-----------------------------|--------------------------|---|--------------|
| Entire vehicle – General | corrosion warranty check | Carry out condition report | |
| Entire vehicle – General | Minor maintenance | Carry out minor service and brake fluid change Carry out drive belt check | |
| Coolant regulator housing | Coolant leaking | | |

Service Job #16 - Porsche Centre Guildford

Service Dates: August 13, 2024 - August 20, 2024

Odometer Value: 52,888 Miles

Breakdown Status: No

Services Performed

| Location | Symptom | Information | Warranty Use |
|---------------------------|---------|-------------|--------------|
| Coolant regulator housing | Leaks | | ✓ |

While we strive for accuracy, VIN Analytics is not responsible for any errors or omissions on this page. Please verify any details with your local Porsche Dealership or Porsche Cars Customer Service. We assume no responsibility for errors in this report and disclaim all warranties, including implied warranties of merchantability or fitness for a particular purpose. All trademarks and registered trademarks are the property of their respective owners. All trademarks, trade names, service marks, product names, option names and logos are the property of their respective owners.

© 2025 VIN Analytics, LLC. All rights reserved.

