

4-wheel Recall, improvement measures, and service campaigns Target vehicle search


The entered chassis number RP3-1007445

The vehicle with the chassis number you entered has had all recalls and other issues carried out, so you can use it with peace of mind.


[Search results: Completed] The following shows the past implementation history.

| Classification       | Notification date<br>(start date) | Notification number | Details (Click below to view details of measures)                    |
|----------------------|-----------------------------------|---------------------|----------------------------------------------------------------------|
| Improvement measures | 2018-11-15 Notification           | 558                 | <a href="#">Tailgate open stay defect Measures</a>                   |
| recall               | 2018-05-31 Notification           | Country 4274        | <a href="#">Master cylinder replacement procedure</a>                |
| Service Campaign     | Started 2017-07-14                | -                   | <a href="#">Transmission control unit inspection and replacement</a> |

■ Inquiries

 クルマ(車両)

■Hondaお客様相談センター

 0120-112010

受付時間:9時～12時/13時～17時

閉じる